TO BE FILLED BY THE INSPECTING OFFICER (Assistant Engineer / Assistant Executive Engineer)

Name of School	Chromaya Vidyalaye, Thalpertumba
1. Name of the Officer	imal bermar . V
2. Location	Theilipenember
3. Period for which the certificate is	issued 2023-24
4. Types of building	permanent building, 1. D 63:00 x 8:5 an (GF, FF, SF)
5. Nature of defect if any	사람이 되는 이 집에 가는 이 사람이 되는 것이 없는 것이 되었다. 그는 것이 없는 것이 없는 것이 되었다고 있는 것이 없는 것이 없는 것이 없는 것이 없는 것이 없는 것이 없는 것이 없다.
a) Foundation and basement	2) 57.40 x8-30 (aF, FF, SF)
b) Superstructure	3, 810 × 7.60 (GIF, FF, SF) 4, 21.90 × 810 (GF, FF, SE)
c) Doors and windows	5, 26-50 x855 (4F, FF)
d) Wood work wrought and put	TNI
e) Roof	
f) Flooring	
g) Miscellaneous (Cracks if any	
6. Any major defects noticed which render the building unsafe in any	n will v manner
7. Whether maintenance work hav done properly	re been yes
8. Whether the structure is sound for conducting classes.	or not Yes, Under Normal weather condess up to 31. 03.24
Note: 1 The Stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood etc.	
2 Any additional observation the Certificate.	tion deemed necessary for the Certificate, may be furnished separately with
Certified that the S	chool was inspected by ne onand found
to be, fit / unfit to conduct classes for the period for the reasons stated above.	

Signature

Designation

Place: Thefle jo man

Date :

Vimal Kumar. V

PEN: 308165

Municipal Engineer

Taliparamba Municipality